

Janahitha - Complaint Details			
Complaint No. :	MYS-JH-ENG-16-17-570145	Registration Date :	12-03-2017
Complaint Category :	ENGINEERING	Complaint Subcategory :	EN5-Road Repairs
ULB :	Mysuru	Ward :	WARD 17
Street :	Adichunchangiri Road	Complaint Location :	Adichunchanagiri Road, 3rd Stage, Kuvempunagar, In front of Yamaha Service Centre
Complaint Details :	Road was dug up for sewage pipe installation and has been closed poorly. Very bad patch up work. All the mud is lying on the street. It is dangerous for the motorists also. Lot of dust causing health hazard. Already 2 or 3 minor accidents have happened.	Complaint Status :	Escalated
Complainant Name :	Narendra Mundath	Complainant Contact No. :	9945798327
Assigned Officer Name :	admin_mysore	Assigned Officer Contact No. :	9449841234
Uploaded File :	Download Uploaded File		